

Print Date: 11/30/2015 13:52

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		88.36	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		167,259	
Heat Type	1		FORCED H/A	AYB		1977	
AC Type	03		FULL	EYB		1985	
Bedrooms	4			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %		29	
Total Rooms	7			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		71	
Basement Floor	12			Apprais Val		118,800	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	64	7.48	2002	A		GD	70	300
SOL	Solar Panels	EX	Extra Feature	B	1	0.00	1985		1		100	0

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	816		17.65	14,402
FFL	1ST FLOOR	864	864		88.36	76,340
PAT	PATIO	0	320		4.42	1,414
SFL	2ND FLOOR	850	850		88.36	75,103
Ttl. Gross Liv/Lease Area:		1,714	2,850	1,893		167,259

