

CURRENT OWNER				TOPO.				UTILITIES				STRT./ROAD				LOCATION				CURRENT ASSESSMENT							
BURACK MARIE R 177 SOMERS RD EAST LONGMEADOW, MA 01028 Additional Owners:						1	TYPCL										Description	Code	Appraised Value	Assessed Value	1006 AST LONGMEADOW, M <						

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.00		1 Story	Int vs Ext	S		
Foundation	6		SLAB	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	1		WOOD SHING	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER	COST/MARKET VALUATION			
Interior Wall 2	1		DRYWALL				
Interior Floor 1	4		CARPET	Adj. Base Rate:		89.64	
Interior Floor 2				Replace Cost164,581 AYB1950 EYB1975 Dep CodeAV Remodel Rating Year Remodeled Dep %39 Functional Obslnc External Obslnc Cost Trend Factor1 Condition % Complete Overall % Cond61 Apprais Val100,400 Dep % Ovr0 Dep Ovr Comment Misc Imp Ovr0 Misc Imp Ovr Comment Cost to Cure Ovr0 Cost to Cure Ovr Comment			
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W				
AC Type	01		NONE				
Bedrooms	3						
Full Baths	2						
Half Baths	0						
Extra Fixtures	0						
Total Rooms	9						
Bath Style	A		AVERAGE				
Kitchen Style	A		AVERAGE				
Kitchens	1						
Extra Kitchens	0						
Frame	1		WOOD				
Basement Floor	12						
Bsmt Garage							
Units	1						
WS Flues	1						
FBM Quality							
Fireplaces	1						

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value						
FFL	1ST FLOOR	1,804	1,804		89.64	161,713						
WDK	WOOD DECK	0	228		12.58	2,869						
Ttl. Gross Liv/Lease Area:		1,804	2,032	1,836		164,581						

