

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	222		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			83.48
Interior Floor 2	4		CARPET				
Heat Fuel	1		OIL	Replace Cost			173,546
Heat Type	3		FORCED H/W	AYB			1950
AC Type	01		NONE	EYB			1987
Bedrooms	5			Dep Code			GD
Full Baths	2			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %			27
Total Rooms	8			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			73
Basement Floor	12			Apprais Val			126,700
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	126	7.48	1955	A		AV	60	600

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	888		16.73	14,859
EFP	ENCL PORCH	0	272		25.17	6,845
FFL	1ST FLOOR	888	888		83.48	74,126
GAR	GARAGE	0	240		33.39	8,014
OPF	OPEN PORCH	0	24		6.96	167
PAT	PATIO	0	339		4.19	1,419
SFL	2ND FLOOR	816	816		83.48	68,116
Ttl. Gross Liv/Lease Area:		1,704	3,467	2,079		173,546

