

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	C		AVERAGE	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			87.12
Interior Floor 2	6		CERAMIC TL				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			204,467
AC Type	03		Full	AYB			1998
Bedrooms	4			EYB			2005
Full Baths	2			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	8			Dep %			9
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond			91
Bsmt Garage	2			Apprais Val			186,100
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,136		17.41	19,776
FFL	1ST FLOOR	1,136	1,136		87.12	98,967
HST	HALF STORY	184	368		43.56	16,030
SFL	2ND FLOOR	800	800		87.12	69,695
Ttl. Gross Liv/Lease Area:		2,120	3,440	2,347		204,467

SFL	32	HST	16
FFL		FFL	
BMT		BMT	
24		2323	23
	32		16
SFL	32		
1			

