

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.50		1 1/2 Stories	Int vs Ext	S		
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	3		ALUMINUM	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD				
Interior Floor 2				Adj. Base Rate:		99.92	
Heat Fuel	1		OIL	Replace Cost		122,006	
Heat Type	1		FORCED H/A			1940	
AC Type	01		NONE			1975	
Bedrooms	2					AV	
Full Baths	1						
Half Baths	0			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	4			Dep %		39	
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond		61	
Bsmt Garage				Apprais Val		74,400	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr		0	
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	96	7.48	1995	A		AV	60	400
2	GAZEBO			L	169	18.00	2000	G		GD	70	2,700

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	814		20.01	16,287
FFL	1ST FLOOR	814	814		99.92	81,337
UHS	UNFIN HALF STORY	0	814		29.95	24,381
Ttl. Gross Liv/Lease Area:		814	2,442	1,221		122,006

