

Vision ID: 4227

Account #4296

Bldg #: 1 of 1

Sec #: 1 of

1 Card 1 of 1

Print Date: 11/30/2015 17:22

CURRENT OWNER				TOPO.		UTILITIES		STRT./ROAD		LOCATION		CURRENT ASSESSMENT							
MURPHY KAREN M 40 SOUTH BEND LN EAST LONGMEADOW, MA 01028 Additional Owners:						1	TYPCL					Description	Code	Appraised Value	Assessed Value	1006 AST LONGMEADOW, M <			

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	19		RANCH	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	420			
Stories	1.00		1 STORY	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	12		BOARD+BATT	Code	Description		Percentage	
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				80.63
Interior Floor 1	3		HARDWOOD	Replace Cost				209,246
Interior Floor 2	4		CARPET					AYB
Heat Fuel	1		OIL	EYB				1980
Heat Type	3		FORCED H/W					Dep Code
AC Type	01		NONE	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	2			Dep %				34
Half Baths	0			Functional Obslnc				
Extra Fixtures	1			External Obslnc				5
Total Rooms	6			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				61
Extra Kitchens	0			Apprais Val				127,600
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	1			Cost to Cure Ovr Comment				
Fireplaces	2							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

Ttl. Gross Liv/Lease Area:		1,734	5,020	2,595		209,246
----------------------------	--	-------	-------	-------	--	---------

