

Print Date: 12/01/2015 09:03

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	C		AVERAGE	FBM Sqft	504		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:		88.36	
Interior Floor 2							
Heat Fuel	2		GAS	Replace Cost		192,354	
Heat Type	1		FORCED H/A	AYB		1992	
AC Type	03		Full	EYB		2002	
Bedrooms	3			Dep Code		GD	
Full Baths	1			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %		12	
Total Rooms	7			Functional ObsInc			
Bath Style	G		GOOD	External ObsInc			
Kitchen Style	G		GOOD	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		88	
Basement Floor				Apprais Val		169,300	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	120	7.48	2003	A		GD	70	600

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	720		17.67	12,723
FFL	1ST FLOOR	1,050	1,050		88.36	92,775
GAR	GARAGE	0	484		35.42	17,141
OFP	OPEN PORCH	0	56		9.47	530
SFL	2ND FLOOR	752	752		88.36	66,445
WDK	WOOD DECK	0	224		12.23	2,739
Ttl. Gross Liv/Lease Area:		1,802	3,286	2,177		192,354

