

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	541		
Stories	1.00		1 Story	Int vs Ext	AV		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		91.21	
Interior Floor 2	5		LINO/VINYL				
Heat Fuel	1		OIL	Replace Cost		170,023	
Heat Type	2		GRAVITY H/A	AYB		1957	
AC Type	01		NONE	EYB		1975	
Bedrooms	3			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %		39	
Total Rooms	6			Functional ObsInc			
Bath Style	A		AVERAGE	External ObsInc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		61	
Basement Floor	12			Apprais Val		103,700	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,352		18.22	24,628
BNT	BSMT ENTRY	0	54		5.07	274
FFL	1ST FLOOR	1,352	1,352		91.21	123,321
GAR	GARAGE	0	525		36.49	19,155
OFF	OPEN PORCH	0	288		9.18	2,645

Ttl. Gross Liv/Lease Area:		1,352	3,571	1,864		170,023
----------------------------	--	-------	-------	-------	--	---------

