

Print Date: 12/01/2015 11:39

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C+		AVG. (+)	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	2		CLAPBOARD	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			92.51
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			201,113
AC Type	03		FULL	AYB			1969
Bedrooms	3			EYB			1990
Full Baths	1			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	7			Dep %			24
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			76
Bsmt Garage				Apprais Val			152,800
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	2			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	978		18.54	18,132	
FFL	1ST FLOOR	978	978		92.51	90,473	
GAR	GARAGE	0	484		37.08	17,947	
OFP	OPEN PORCH	0	60		9.25	555	
SFL	2ND FLOOR	800	800		92.51	74,007	
Ttl. Gross Liv/Lease Area:		1,778	3,300	2,174		201,113	
