

Print Date: 12/01/2015 15:58

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	558		
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			78.20
Interior Floor 2	6		CERAMIC TL				
Heat Fuel	2		GAS				
Heat Type	3		FORCED H/W	Replace Cost			261,201
AC Type	03		FULL	AYB			1964
Bedrooms	5			EYB			1987
Full Baths	2			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	9			Dep %			27
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			73
Bsmt Garage				Apprais Val			190,700
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr			0
Fireplaces	2			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
01	SHED/MTL			L	72	5.18	1985	A		AV	60	200

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value						
BMT	BASEMENT	0	1,116		15.63	17,439						
FFL	1ST FLOOR	1,824	1,824		78.20	142,644						
GAR	GARAGE	0	660		31.28	20,646						
OPF	OPEN PORCH	0	80		7.82	626						
PAT	PATIO	0	250		4.07	1,017						
SFL	2ND FLOOR	1,008	1,008		78.20	78,830						
Ttl. Gross Liv/Lease Area:		2,832	4,938	3,340		261,201						

