

Print Date: 12/01/2016 10:09

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	15		OLD STYLE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	414			
Stories	2.00		2 Story	Int vs Ext	S			
Foundation	2		CONC BLOCK	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	3		GAMBREL	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2	2		PLASTER	Adj. Base Rate:				72.65
Interior Floor 1	3		HARDWOOD	Replace Cost				131,489
Interior Floor 2	4		CARPET	AYB				1900
Heat Fuel	1		OIL	EYB				1975
Heat Type	5		STEAM	Dep Code				AV
AC Type	01		NONE	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	1			Dep %				39
Half Baths	0			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	5			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				61
Extra Kitchens	0			Apprais Val				80,200
Frame	1		WOOD	Dep % Ovr				0
Basement Floor				Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	3			Cost to Cure Ovr Comment				
Fireplaces	0							

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value						
BMT	BASEMENT	0	828		14.56	12,059						
EFP	ENCL PORCH	0	70		21.79	1,526						
FFL	1ST FLOOR	828	828		72.65	60,151						
OFF	OPEN PORCH	0	84		6.92	581						
SFL	2ND FLOOR	787	787		72.65	57,172						
Ttl. Gross Liv/Lease Area:		1,615	2,597	1,810			131,489					

