

Vision ID: 1607

Account #1642

Bldg #: 1 of 1

Sec #: 1 of

1 Card 1 of 1

Print Date: 12/01/2016 13:10

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	583		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			95.60
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			165,382
AC Type	03		FULL	AYB			1994
Bedrooms	3			EYB			2003
Full Baths	1			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	6			Dep %			11
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			89
Bsmt Garage				Apprais Val			147,200
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr			0
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	160	7.48	2000	G		GD	70	1,000
08	POOL A-O			L	30	69.00	2014	A		GD	70	1,400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	777		19.07	14,817	
FFL	1ST FLOOR	777	777		95.60	74,278	
SFL	2ND FLOOR	768	768		95.60	73,418	
WDK	WOOD DECK	0	217		13.22	2,868	
Ttl. Gross Liv/Lease Area:		1,545	2,539	1,730		165,382	

