

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	576		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		90.51	
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS	Replace Cost		182,292	
Heat Type	5		STEAM	AYB		1940	
AC Type	03		FULL	EYB		1987	
Bedrooms	3			Dep Code		GD	
Full Baths	2			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %		27	
Total Rooms	7			Functional ObsInc			
Bath Style	A		AVERAGE	External ObsInc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		73	
Basement Floor	12		CONCRETE	Apprais Val		133,100	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
04	GARAGE/L			L	576	30.48	1998	G		GD	70	15,400
02	SHED/FR			L	240	7.48	2012	A		GD	70	1,300

[illegible]

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	768		18.15	13,935
EFP	ENCL PORCH	0	80		27.15	2,172
FFL	1ST FLOOR	853	853		90.51	77,207
PAT	PATIO	0	683		4.51	3,077
SFL	2ND FLOOR	864	864		90.51	78,203
WDK	WOOD DECK	0	608		12.65	7,694

[illegible][illegible]

--	--	--	--	--	--	--

<i>Ttl Gross Liv/Lease Area:</i>	1.717	3.856	2.014		182.292

