

Print Date: 12/02/2016 14:26

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	18		SPLIT ENT	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	806		
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:			114.47
Interior Floor 2	3		HARDWOOD	Replace Cost AYB EYB Dep Code Remodel Rating Year Remodeled Dep % Functional Obslnc External Obslnc Cost Trend Factor Condition % Complete Overall % Cond Apprais Val Dep % Ovr Dep Ovr Comment Misc Imp Ovr Misc Imp Ovr Comment Cost to Cure Ovr Cost to Cure Ovr Comment			
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W				
AC Type	01		NONE				
Bedrooms	2						
Full Baths	2						
Half Baths	0						
Extra Fixtures	0						
Total Rooms	6						
Bath Style	A		AVERAGE				
Kitchen Style	A		AVERAGE				
Kitchens	2						
Extra Kitchens	0						
Frame	1		WOOD				
Basement Floor	6		CERAMIC TILE				
Bsmt Garage	1						
Units	1						
WS Flues							
FBM Quality	3						
Fireplaces	2						

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
FFL	1ST FLOOR	1,242	1,242		114.47	142,167	
LLV	LOWR LEVEL	0	1,152		28.62	32,966	
PAT	PATIO	0	144		5.56	801	
Ttl. Gross Liv/Lease Area:		1,242	2,538	1,537		175,935	

