

Vision ID: 3620

Account #3679

Bldg #: 1 of 1

Sec #: 1 of

1 Card 1 of 1

Print Date: 12/02/2016 14:50

CURRENT OWNER				TOPO.				UTILITIES				STRT./ROAD				LOCATION				CURRENT ASSESSMENT								1006 AST LONGMEADOW, MA 			
---------------	--	--	--	-------	--	--	--	-----------	--	--	--	------------	--	--	--	----------	--	--	--	--------------------	--	--	--	--	--	--	--	--	--	--	--

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		
Grade	B		GOOD	FBM Sqft	431		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	2		HIP				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			98.03
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			299,766
AC Type	03		Full	AYB			1998
Bedrooms	4			EYB			2005
Full Baths	2			Dep Code			GD
Half Baths	2			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	8			Dep %		9	
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12			Overall % Cond		91	
Bsmt Garage				Apprais Val		272,800	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr		0	
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

