

Print Date: 12/02/2016 18:13

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	395		
Stories	1.5			Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2	8		PLYWD PANL	COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		95.26	
Interior Floor 2	5		LINO/VINYL				
Heat Fuel	1		OIL	Replace Cost		151,170	
Heat Type	1		FORCED H/A	AYB		1954	
AC Type	01		NONE	EYB		1975	
Bedrooms	2			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	1			Dep %		39	
Total Rooms	5			Functional ObsInc			
Bath Style	G		GOOD	External ObsInc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		61	
Basement Floor	12		CONCRETE	Apprais Val		92,200	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
19	PATIO			L	380	5.75	1963	A		AV	60	1,300
02	SHED/FR			L	120	7.48	2002	A		GD	70	600

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
ATC	ATTIC	247	988		23.81	23,528	
BMT	BASEMENT	0	988		19.09	18,861	
EFP	ENCL PORCH	0	96		28.78	2,762	
FFL	1ST FLOOR	988	988		95.26	94,112	
GAR	GARAGE	0	312		38.16	11,907	
Ttl. Gross Liv/Lease Area:		1,235	3,372	1,587		151,170	

