

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B		GOOD	FBM Sqft	293		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	3		GAMBREL	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			100.38
Interior Floor 2	4		CARPET				
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W	Replace Cost			243,316
AC Type	01		NONE	AYB			1977
Bedrooms	4			EYB			1994
Full Baths	1			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	8			Dep %			20
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			80
Bsmt Garage				Apprais Val			194,700
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	100	7.48	1996	G		GD	70	700

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	978		20.12	19,674	
FFL	1ST FLOOR	978	978		100.38	98,170	
GAR	GARAGE	0	506		40.07	20,276	
OFP	OPEN PORCH	0	60		10.04	602	
SFL	2ND FLOOR	790	790		100.38	79,299	
STG	STORAGE	0	526		40.07	21,079	
WDK	WOOD DECK	0	300		14.05	4,216	
Ttl. Gross Liv/Lease Area:		1,768	4,138	2,424		243,316	

