


CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	06		COLONIAL	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	425			
Stories	2.00		2 STORY	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				98.56
Interior Floor 1	4		CARPET	Replace Cost				154,941
Interior Floor 2	3		HARDWOOD					
Heat Fuel	2		GAS					
Heat Type	1		FORCED H/A	AYB				1994
AC Type	03		FULL					
Bedrooms	3							
Full Baths	1			EYB				2003
Half Baths	1							
Extra Fixtures	0							
Total Rooms	6			Dep Code				GD
Bath Style	A		AVERAGE					
Kitchen Style	A		AVERAGE					
Kitchens	1			Remodel Rating				
Extra Kitchens	0							
Frame	1		WOOD					
Basement Floor	12		CONCRETE	Year Remodeled				
Bsmt Garage								
Units	1							
WS Flues				Dep %				11
FBM Quality	3							
Fireplaces	0							
				Functional Obslnc				
				External Obslnc				
				Cost Trend Factor				1
				Condition				
				% Complete				
				Overall % Cond				89
				Apprais Val				137,900
				Dep % Ovr				0
				Dep Ovr Comment				
				Misc Imp Ovr				0
				Misc Imp Ovr Comment				
				Cost to Cure Ovr				0
				Cost to Cure Ovr Comment				

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	120	7.48	2002	A		GD	70	600

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	708		19.77	13,996
FFL	1ST FLOOR	708	708		98.56	69,783
PAT	PATIO	0	288		4.79	1,380
SFL	2ND FLOOR	708	708		98.56	69,783
Ttl. Gross Liv/Lease Area:		1,416	2,412	1,572		154,941



2007 10 15