

Print Date: 12/06/2016 16:13

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	648		
Stories	1.00		1 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			121.78
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost			130,183
Heat Type	3		FORCED H/W	AYB			1952
AC Type	01		NONE	EYB			1980
Bedrooms	3			Dep Code			AG
Full Baths	1			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %			34
Total Rooms	5			Functional ObsInc			
Bath Style	A		AVERAGE	External ObsInc			
Kitchen Style	A		AVERAGE	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			66
Basement Floor	12			Apprais Val			85,900
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	864		24.38	21,068
FFL	1ST FLOOR	864	864		121.78	105,218
WDK	WOOD DECK	0	228		17.09	3,897
Ttl. Gross Liv/Lease Area:		864	1,956	1,069		130,183

