

Print Date: 12/06/2016 16:15

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	738		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			81.96
Interior Floor 2	3		HARDWOOD				
Heat Fuel	1		OIL	Replace Cost			221,537
Heat Type	1		FORCED H/A	AYB			1977
AC Type	03		FULL	EYB			1994
Bedrooms	3			Dep Code			GD
Full Baths	2			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	1			Dep %			20
Total Rooms	7			Functional Obslnc			
Bath Style	G		GOOD	External Obslnc			
Kitchen Style	G		GOOD	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			80
Basement Floor	12		CONCRETE	Apprais Val			177,200
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality	1			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	96	7.48	2013	A		AV	60	400

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,344		16.40	22,047
CPT	CARPORT	0	384		8.11	3,114
FFL	1ST FLOOR	984	984		81.96	80,648
OFP	OPEN PORCH	0	88		8.38	738
SFL	2ND FLOOR	1,344	1,344		81.96	110,154
WDK	WOOD DECK	0	424		11.40	4,836

Ttl. Gross Liv/Lease Area:		2,328	4,568	2,703	221,537

