

[illegible]

CONSTRUCTION DETAIL			CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	2		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B-		GOOD (-)	FBM Sqft	524		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			103.34
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			258,049
AC Type	03		FULL	AYB			1987
Bedrooms	4			EYB			1999
Full Baths	3			Dep Code			GD
Half Baths	1			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	8			Dep %			15
Bath Style	G		GOOD	Functional ObsInc			
Kitchen Style	G		GOOD	External ObsInc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			85
Bsmt Garage				Apprais Val			219,300
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
11	POOL I-V	OB	Outbuilding	L	576	29.00	1997	G		GD	70	14,600

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,048		20.71	21,702
CFL	CATHEDRAL CE	280	280		106.30	29,763
FFL	1ST FLOOR	912	912		103.34	94,245
GAR	GARAGE	0	576		41.27	23,765
OSP	SCRN PORCH	0	168		15.38	2,584
SFL	2ND FLOOR	832	832		103.34	85,982

Ttl. Gross Liv/Lease Area:		2,024	3,816	2,497		258,045

