

Print Date: 12/07/2016 09:16

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	408		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:			88.26
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	3		FORCED H/W	Replace Cost			184,997
AC Type	01		NONE	AYB			1965
Bedrooms	4			EYB			1988
Full Baths	2			Dep Code			GD
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	7			Dep %			26
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			74
Bsmt Garage				Apprais Val			136,900
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	1			Misc Imp Ovr			0
Fireplaces	2			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	64	7.48	1990	A		AV	60	300

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	816		17.63	14,387
EFP	ENCL PORCH	0	264		26.41	6,973
FFL	1ST FLOOR	816	816		88.26	72,022
GAR	GARAGE	0	440		35.30	15,534
SFL	2ND FLOOR	850	850		88.26	75,023
WDK	WOOD DECK	0	84		12.61	1,059
Ttl. Gross Liv/Lease Area:		1,666	3,270	2,096		184,997

