

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	06		COLONIAL	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	B-		GOOD (-)	FBM Sqft	502			
Stories	2.00		2 STORY	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				94.94
Interior Floor 1	3		HARDWOOD	Replace Cost				267,723
Interior Floor 2	4		CARPET	AYB				2006
Heat Fuel	2		GAS	EYB				2010
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	2			Dep %				4
Half Baths	1			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	G		GOOD	Condition				
Kitchen Style	G		GOOD	% Complete				
Kitchens	1			Overall % Cond				96
Extra Kitchens	0			Apprais Val				257,000
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality	3			Cost to Cure Ovr Comment				
Fireplaces	1							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)											
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,040		18.99	19,747
FFL	1ST FLOOR	1,040	1,040		94.94	98,735
GAR	GARAGE	0	576		37.91	21,836
HST	HALF STORY	288	576		47.47	27,342
SFL	2ND FLOOR	1,040	1,040		94.94	98,735
WDK	WOOD DECK	0	100		13.29	1,329

Ttl. Gross Liv/Lease Area:		2,368	4,372	2,820		267,723
----------------------------	--	-------	-------	-------	--	---------

