


VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B-		GOOD (-)	FBM Sqft			
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1			MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:			90.21
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS	Replace Cost			282,005
Heat Type	1		FORCED H/A	AYB			2006
AC Type	03		FULL	EYB			2010
Bedrooms	4			Dep Code			GD
Full Baths	2			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	2			Dep %			4
Total Rooms	7			Functional Obslnc			
Bath Style	G		GOOD	External Obslnc			
Kitchen Style	G		GOOD	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			96
Basement Floor	12			Apprais Val			270,700
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

Ttl. Gross Liv/Lease Area:		2,537	5,226	3,126		282,005
----------------------------	--	-------	-------	-------	--	---------



2007 4 21