

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	06		COLONIAL	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C+		AVG. (+)	FBM Sqft				
Stories	2.00		2 STORY	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				94.55
Interior Floor 1	3		HARDWOOD	Replace Cost				222,768
Interior Floor 2	4		CARPET	AYB				2010
Heat Fuel	2		GAS	EYB				2012
Heat Type	1		FORCED H/A	Dep Code				GD
AC Type	03		FULL	Remodel Rating				
Bedrooms	4			Year Remodeled				
Full Baths	2			Dep %				2
Half Baths	1			Functional Obslnc				
Extra Fixtures	1			External Obslnc				
Total Rooms	6			Cost Trend Factor				1
Bath Style	G		GOOD	Condition				
Kitchen Style	G		GOOD	% Complete				
Kitchens	1			Overall % Cond				98
Extra Kitchens	0			Apprais Val				218,300
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality				Cost to Cure Ovr Comment				
Fireplaces	1							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)																
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value				

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	866		18.89	16,358	
FFL	1ST FLOOR	866	866		94.55	81,883	
GAR	GARAGE	0	440		37.82	16,641	
SFL	2ND FLOOR	1,118	1,118		94.55	105,711	
WDK	WOOD DECK	0	166		13.10	2,175	
Ttl. Gross Liv/Lease Area:		1,984	3,456	2,356		222,768	

