

Print Date: 11/30/2016 17:18

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	288		
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			89.19
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			175,530
AC Type	01		NONE	AYB			1954
Bedrooms	4			EYB			1975
Full Baths	2			Dep Code			AV
Half Baths	0			Remodel Rating			
Extra Fixtures	1			Year Remodeled			
Total Rooms	7			Dep %			39
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond			61
Bsmt Garage				Apprais Val			107,100
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality	1			Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	96	7.48	1970	A		AV	60	400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	960		17.84	17,125	
FFL	1ST FLOOR	1,056	1,056		89.19	94,187	
TQS	3/4 STORY	720	960		66.89	64,218	
Ttl. Gross Liv/Lease Area:		1,776	2,976	1,968		175,530	

