

## VISION

| CONSTRUCTION DETAIL |      |     |             | CONSTRUCTION DETAIL (CONTINUED) |             |     |             |
|---------------------|------|-----|-------------|---------------------------------|-------------|-----|-------------|
| Element             | Cd.  | Ch. | Description | Element                         | Cd.         | Ch. | Description |
| Style               | 19   |     | RANCH       | #Heat Sys                       | 1           |     |             |
| Model               | 01   |     | RESIDENTIAL | Central Vac                     | 0           |     | NO          |
| Grade               | C    |     | AVERAGE     | FBM Sqft                        | 676         |     |             |
| Stories             | 1.00 |     | 1 STORY     | Int vs Ext                      | S           |     | SAME        |
| Foundation          | 1    |     | CONCRETE    | MIXED USE                       |             |     |             |
| Exterior Wall 1     | 4    |     | VINYL       | Code                            | Description |     | Percentage  |
| Exterior Wall 2     | 8    |     | BRICK VENR  | 101                             | ONE FAM     |     | 100         |
| Roof Structure      | 1    |     | GABLE       |                                 |             |     |             |
| Roof Cover          | 1    |     | ASPHALT SH  |                                 |             |     |             |
| Interior Wall 1     | 1    |     | DRYWALL     |                                 |             |     |             |
| Interior Wall 2     |      |     |             | COST/MARKET VALUATION           |             |     |             |
| Interior Floor 1    | 4    |     | CARPET      | Adj. Base Rate:                 |             |     | 102.81      |
| Interior Floor 2    | 3    |     | HARDWOOD    |                                 |             |     |             |
| Heat Fuel           | 1    |     | OIL         |                                 |             |     |             |
| Heat Type           | 3    |     | FORCED H/W  | Replace Cost                    |             |     | 154,422     |
| AC Type             | 03   |     | FULL        | AYB                             |             |     | 1958        |
| Bedrooms            | 3    |     |             | EYB                             |             |     | 1980        |
| Full Baths          | 1    |     |             | Dep Code                        |             |     | AG          |
| Half Baths          | 1    |     |             | Remodel Rating                  |             |     |             |
| Extra Fixtures      | 0    |     |             | Year Remodeled                  |             |     |             |
| Total Rooms         | 6    |     |             | Dep %                           |             |     | 34          |
| Bath Style          | A    |     | AVERAGE     | Functional Obslnc               |             |     |             |
| Kitchen Style       | A    |     | AVERAGE     | External Obslnc                 |             |     | 5           |
| Kitchens            | 1    |     |             | Cost Trend Factor               |             |     | 1           |
| Extra Kitchens      | 0    |     |             | Condition                       |             |     |             |
| Frame               | 1    |     | WOOD        | % Complete                      |             |     |             |
| Basement Floor      |      |     |             | Overall % Cond                  |             |     | 61          |
| Bsmt Garage         |      |     |             | Apprais Val                     |             |     | 94,200      |
| Units               | 1    |     |             | Dep % Ovr                       |             |     | 0           |
| WS Flues            |      |     |             | Dep Ovr Comment                 |             |     |             |
| FBM Quality         | 3    |     |             | Misc Imp Ovr                    |             |     | 0           |
| Fireplaces          | 0    |     |             | Misc Imp Ovr Comment            |             |     |             |
|                     |      |     |             | Cost to Cure Ovr                |             |     | 0           |
|                     |      |     |             | Cost to Cure Ovr Comment        |             |     |             |

| BUILDING SUB-AREA SUMMARY SECTION |             |             |            |           |           |                 |  |
|-----------------------------------|-------------|-------------|------------|-----------|-----------|-----------------|--|
| Code                              | Description | Living Area | Gross Area | Eff. Area | Unit Cost | Undeprec. Value |  |
| BMT                               | BASEMENT    | 0           | 990        |           | 20.56     | 20,357          |  |
| FFL                               | 1ST FLOOR   | 1,134       | 1,134      |           | 102.81    | 116,588         |  |
| GAR                               | GARAGE      | 0           | 308        |           | 41.06     | 12,646          |  |
| OFP                               | OPEN PORCH  | 0           | 24         |           | 8.57      | 206             |  |
| WDK                               | WOOD DECK   | 0           | 322        |           | 14.37     | 4,626           |  |
| Ttl. Gross Liv/Lease Area:        |             | 1,134       | 2,778      | 1,502     |           | 154,422         |  |

