

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				89.35
Interior Floor 1	3		HARDWOOD	Replace Cost				161,458
Interior Floor 2				AYB				1952
Heat Fuel	1		OIL	EYB				1975
Heat Type	1		FORCED H/A	Dep Code				AV
AC Type	01		NONE	Remodel Rating				
Bedrooms	4			Year Remodeled				
Full Baths	1			Dep %				39
Half Baths	1			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				61
Extra Kitchens	0			Apprais Val				98,500
Frame	1		WOOD	Dep % Ovr				0
Basement Floor				Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality				Cost to Cure Ovr Comment				
Fireplaces	1							

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	912		17.83	16,262	
EFP	ENCL PORCH	0	96		26.99	2,591	
FFL	1ST FLOOR	912	912		89.35	81,488	
TQS	3/4 STORY	684	912		67.01	61,116	
Ttl. Gross Liv/Lease Area:		1,596	2,832	1,807		161,458	

TQS	38	EFP	8
FFL			
BMT			
		1212	12
			8
24			
		12	
	38		

