

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C-		AVG. (-)	FBM Sqft	504		
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		117.04	
Interior Floor 2							
Heat Fuel	1		OIL	Replace Cost		108,028	
Heat Type	1		FORCED H/A	AYB		1950	
AC Type	01		NONE	EYB		1975	
Bedrooms	2			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		39	
Total Rooms	4			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		61	
Basement Floor				Apprais Val		65,900	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	96	7.48	1996	A		AV	60	400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	720		23.41	16,854	
EFP	ENCL PORCH	0	165		35.47	5,852	
FFL	1ST FLOOR	720	720		117.04	84,269	
OFP	OPEN PORCH	0	90		11.70	1,053	
Ttl. Gross Liv/Lease Area:		720	1,695	923		108,028	

