


Print Date: 12/14/2017 20:41

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			98.26
Interior Floor 2	6		CERAMIC TL				
Heat Fuel	2		GAS				
Heat Type	3		FORCED H/W	Replace Cost			157,909
AC Type	01		NONE	AYB			1958
Bedrooms	3			EYB			1980
Full Baths	1			Dep Code			AG
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	6			Dep %			37
Bath Style	A		AVERAGE	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor				Overall % Cond			63
Bsmt Garage				Apprais Val			99,500
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

Ttl. Gross Liv/Lease Area:		1,260	2,688	1,607		157,909
----------------------------	--	-------	-------	-------	--	---------



2006 9 6