

Print Date: 12/14/2017 22:36

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	605		
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	4		CARPET	Adj. Base Rate:		96.61	
Interior Floor 2	3		HARDWOOD				
Heat Fuel	1		OIL				
Heat Type	3		FORCED H/W	Replace Cost		197,478	
AC Type	03		FULL	AYB		1948	
Bedrooms	3			EYB		2009	
Full Baths	2			Dep Code		GD	
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	7			Dep %		8	
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	G		GOOD	External ObsInc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond		92	
Bsmt Garage				Apprais Val		181,700	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr		0	
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			