

Print Date: 12/15/2017 14:07

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	19		RANCH	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.00		1 STORY	Int vs Ext	S		SAME
Foundation	6		SLAB	MIXED USE			
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	2		HIP	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD				
Interior Floor 2				Adj. Base Rate:		97.39	
Heat Fuel	1		OIL	Replace Cost		159,814	
Heat Type	3		FORCED H/W	AYB		1957	
AC Type	01		NONE	EYB		1974	
Bedrooms	4			Dep Code		AV	
Full Baths	1			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	0			Dep %		43	
Total Rooms	7			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc			
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		57	
Basement Floor				Apprais Val		91,100	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	160	7.48	2000	G		GD	70	1,000

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
FFL	1ST FLOOR	1,482	1,482		97.39	144,329	
GAR	GARAGE	0	312		39.02	12,174	
OPF	OPEN PORCH	0	72		9.47	682	
WDK	WOOD DECK	0	196		13.42	2,629	
Ttl. Gross Liv/Lease Area:		1,482	2,062	1,641		159,814	

