

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	02		BUNGALOW	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.00		1 STORY	Int vs Ext	S		SAME	
Foundation	2		CONC BLOCK	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	2		PLASTER					
Interior Wall 2								
Interior Floor 1	3		HARDWOOD					
Interior Floor 2	5		LINO/VINYL	Adj. Base Rate:				71.63
Heat Fuel	1		OIL	Replace Cost				185,663
Heat Type	1		FORCED H/A	AYB				1930
AC Type	01		NONE	EYB				1974
Bedrooms	2			Dep Code				AV
Full Baths	2			Remodel Rating				
Half Baths	0			Year Remodeled				
Extra Fixtures	1			Dep %				43
Total Rooms	5			Functional Obslnc				
Bath Style	A		AVERAGE	External Obslnc				
Kitchen Style	A		AVERAGE	Cost Trend Factor				1
Kitchens	1			Condition				
Extra Kitchens	0			% Complete				
Frame	1		WOOD	Overall % Cond				57
Basement Floor				Apprais Val				105,800
Bsmt Garage				Dep % Ovr				0
Units	1			Dep Ovr Comment				
WS Flues	1			Misc Imp Ovr				0
FBM Quality				Misc Imp Ovr Comment				
Fireplaces	0			Cost to Cure Ovr				0
				Cost to Cure Ovr Comment				

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	200	7.48	1975	F		PR	30	400

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,552		14.31	22,205	
FFL	1ST FLOOR	1,838	1,838		71.63	131,654	
GAR	GARAGE	0	1,020		28.65	29,225	
WDK	WOOD DECK	0	255		10.11	2,579	
Ttl. Gross Liv/Lease Area:		1,838	4,665	2,592		185,663	

