


CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B-		GOOD (-)	FBM Sqft	260		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			108.96
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A				
AC Type	03		FULL				
Bedrooms	4			Replace Cost	250,380		
Full Baths	2			AYB	2005		
Half Baths	1			EYB	2010		
Extra Fixtures	0			Dep Code	GD		
Total Rooms	8			Remodel Rating			
Bath Style	G		GOOD	Year Remodeled			
Kitchen Style	G		GOOD	Dep %	7		
Kitchens	1			Functional ObsInc			
Extra Kitchens	0			External ObsInc			
Frame	1		WOOD	Cost Trend Factor	1		
Basement Floor	12		CONCRETE	Condition			
Bsmt Garage	2			% Complete			
Units	1			Overall % Cond	93		
WS Flues				Apprais Val	232,900		
FBM Quality	1			Dep % Ovr	0		
Fireplaces	1			Dep Ovr Comment			
				Misc Imp Ovr	0		
				Misc Imp Ovr Comment			
				Cost to Cure Ovr	0		
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,040		21.79	22,663
FFL	1ST FLOOR	1,040	1,040		108.96	113,314
PAT	PATIO	0	196		5.56	1,090
SFL	2ND FLOOR	1,040	1,040		108.96	113,314

Ttl. Gross Liv/Lease Area:		2,080	3,316	2,298		250,380
----------------------------	--	-------	-------	-------	--	---------



2009 7 8