

Print Date: 12/15/2017 17:25

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	B		GOOD	FBM Sqft	209		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	2		HIP				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL	COST/MARKET VALUATION			
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		98.24	
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost		373,886	
AC Type	03		FULL	AYB		1994	
Bedrooms	4			EYB		2003	
Full Baths	3			Dep Code		GD	
Half Baths	1			Remodel Rating			
Extra Fixtures	2			Year Remodeled			
Total Rooms	10			Dep %		14	
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	G		GOOD	External Obslnc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond		86	
Bsmt Garage				Apprais Val		321,500	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality	1			Misc Imp Ovr		0	
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

Ttl. Gross Liv/Lease Area:					3,058	6,321	3,806					373,886
----------------------------	--	--	--	--	-------	-------	-------	--	--	--	--	---------

