

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft	494			
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				88.31
Interior Floor 1	3		HARDWOOD	Replace Cost				206,906
Interior Floor 2				AYB				1961
Heat Fuel	1		OIL	EYB				1980
Heat Type	3		FORCED H/W	Dep Code				AG
AC Type	01		NONE	Remodel Rating				
Bedrooms	4			Year Remodeled				
Full Baths	1			Dep %				37
Half Baths	1			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	7			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				63
Extra Kitchens	0			Apprais Val				130,400
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues	1			Cost to Cure Ovr				0
FBM Quality	1			Cost to Cure Ovr Comment				
Fireplaces	1							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

Ttl. Gross Liv/Lease Area:		1,899	3,880	2,343		206,906
----------------------------	--	-------	-------	-------	--	---------

