

CONSTRUCTION DETAIL			CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	2		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	B-		GOOD (-)	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	2		CLAPBOARD	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL	COST/MARKET VALUATION			
Interior Wall 2				Adj. Base Rate:			97.01
Interior Floor 1	3		HARDWOOD				
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS	Replace Cost			299,652
Heat Type	1		FORCED H/A	AYB			1991
AC Type	03		FULL	EYB			2002
Bedrooms	4			Dep Code			GD
Full Baths	3			Remodel Rating			
Half Baths	0			Year Remodeled			
Extra Fixtures	1			Dep %			15
Total Rooms	8			Functional ObsInc			
Bath Style	G		GOOD	External ObsInc			
Kitchen Style	G		GOOD	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			85
Basement Floor	12		CONCRETE	Apprais Val			254,700
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality				Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION

<i>Code</i>	<i>Description</i>	<i>Living Area</i>	<i>Gross Area</i>	<i>Eff. Area</i>	<i>Unit Cost</i>	<i>Undeprec. Value</i>
BMT	BASEMENT	0	1,396		19.39	27,065
EFP	ENCL PORCH	0	268		28.96	7,760
FFL	1ST FLOOR	1,420	1,420		97.01	137,749
GAR	GARAGE	0	710		38.80	27,550
OFP	OPEN PORCH	0	60		9.70	582
SFL	2ND FLOOR	1,020	1,020		97.01	98,946

--	--	--	--	--	--	--	--

[illegible][illegible]

<i>Ttl. Gross Liv/Lease Area:</i>	2,440	4,874	3,089		299,652
--	--------------	--------------	--------------	--	----------------

