

VISION

CONSTRUCTION DETAIL			CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	B-		GOOD (-)	FBM Sqft	673		
Stories	2.00		2 Story	Int vs Ext	S		
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			98.99
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A				
AC Type	03		Full				
Bedrooms	4			Replace Cost			303,704
Full Baths	2			AYB			1999
Half Baths	1			EYB			2011
Extra Fixtures	2			Dep Code			VG
Total Rooms	9			Remodel Rating			
Bath Style	G		GOOD	Year Remodeled			
Kitchen Style	G		GOOD	Dep %			6
Kitchens	1			Functional ObsInc			
Extra Kitchens	0			External ObsInc			
Frame	1		WOOD	Cost Trend Factor			1
Basement Floor	12			Condition			
Bsmt Garage				% Complete			
Units	1			Overall % Cond			94
WS Flues				Apprais Val			285,500
FBM Quality	1			Dep % Ovr			0
Fireplaces	1			Dep Ovr Comment			
				Misc Imp Ovr			0
				Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	144	7.48	2003	G		GD	70	900

BUILDING SUB-AREA SUMMARY SECTION

<i>Code</i>	<i>Description</i>	<i>Living Area</i>	<i>Gross Area</i>	<i>Eff. Area</i>	<i>Unit Cost</i>	<i>Undeprec. Value</i>
BMT	BASEMENT	0	1,121		19.78	22,174
FFL	1ST FLOOR	1,152	1,152		98.99	114,038
GAR	GARAGE	0	484		39.68	19,204
PAT	PATIO	0	289		4.80	1,386
SFL	2ND FLOOR	1,121	1,121		98.99	110,968
TQS	3/4 STORY	363	484		74.24	35,934

--	--	--	--	--	--	--

[illegible]