

Property Location: 60 SENECA PL										MAP ID: 59/ 71/ 12/ /										Bldg Name:										State Use: 101																													
Vision ID: 6320										Account #6407										Bldg #: 1 of 1										Sec #: 1 of 1										Card 1 of 1										Print Date: 12/16/2017 06:05									
CURRENT OWNER										TOPO.			UTILITIES			STRT./ROAD			LOCATION			CURRENT ASSESSMENT										1006 4ST LONGMEADOW, M 																											

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B		GOOD	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	8		BRICK VENR	101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:		95.29	
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A				
AC Type	03		FULL	Replace Cost	374,305		
Bedrooms	3			AYB	2001		
Full Baths	2			EYB	2007		
Half Baths	1			Dep Code	GD		
Extra Fixtures	3			Remodel Rating			
Total Rooms	8			Year Remodeled			
Bath Style	G		GOOD	Dep %	10		
Kitchen Style	G		GOOD	Functional Obslnc			
Kitchens	1			External Obslnc			
Extra Kitchens	0			Cost Trend Factor	1		
Frame	1		WOOD	Condition			
Basement Floor	12		CONCRETE	% Complete			
Bsmt Garage				Overall % Cond	90		
Units	1			Apprais Val	336,900		
WS Flues				Dep % Ovr	0		
FBM Quality				Dep Ovr Comment			
Fireplaces	1			Misc Imp Ovr	0		
				Misc Imp Ovr Comment			
				Cost to Cure Ovr	0		
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

