

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B		GOOD	FBM Sqft	801		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			108.16
Interior Floor 2							
Heat Fuel	2		GAS	Replace Cost			345,997
Heat Type	1		FORCED H/A	AYB			2003
AC Type	03		FULL	EYB			2009
Bedrooms	4			Dep Code			GD
Full Baths	3			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	2			Dep %			8
Total Rooms	8			Functional Obslnc			
Bath Style	G		GOOD	External Obslnc			
Kitchen Style	G		GOOD	Cost Trend Factor			1
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond			92
Basement Floor	12		CONCRETE	Apprais Val			318,300
Bsmt Garage				Dep % Ovr			0
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr			0
FBM Quality	4			Misc Imp Ovr Comment			
Fireplaces	1			Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)

Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
19	PATIO			L	435	5.75	2005	A		GD	70	1,800

BUILDING SUB-AREA SUMMARY SECTION

Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	1,232		21.60	26,607
CFL	CATHEDRAL CE	120	120		111.76	13,412
FFL	1ST FLOOR	1,112	1,112		108.16	120,272
GAR	GARAGE	0	672		43.30	29,094
HST	HALF STORY	336	672		54.08	36,341
SFL	2ND FLOOR	1,112	1,112		108.16	120,272

Ttl. Gross Liv/Lease Area:		2,680	4,920	3,199		345,997
----------------------------	--	-------	-------	-------	--	---------

