

Print Date: 12/14/2017 16:44

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	2		CONC BLOCK	MIXED USE				
Exterior Wall 1	3		ALUMINUM	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				99.04
Interior Floor 1	4		CARPET	Replace Cost AYB EYB Dep Code Remodel Rating Year Remodeled Dep % Functional Obslnc External Obslnc Cost Trend Factor Condition % Complete Overall % Cond Apprais Val Dep % Ovr Dep Ovr Comment Misc Imp Ovr Misc Imp Ovr Comment Cost to Cure Ovr Cost to Cure Ovr Comment				178,974
Interior Floor 2	3		HARDWOOD					1950
Heat Fuel	2		GAS					1980
Heat Type	1		FORCED H/A					AG
AC Type	03		FULL					
Bedrooms	4							
Full Baths	2							
Half Baths	0							
Extra Fixtures	1							37
Total Rooms	7							
Bath Style	A		AVERAGE					
Kitchen Style	A		AVERAGE					1
Kitchens	1							
Extra Kitchens	0							
Frame	1		WOOD					63
Basement Floor	12		CONCRETE					112,800
Bsmt Garage								0
Units	1							0
WS Flues								
FBM Quality								0
Fireplaces	1							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
03	GARAGE	OB	Outbuilding	L	240	28.18	1950	A		AV	60	4,100

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	912		19.77	18,026
EFP	ENCL PORCH	0	96		29.92	2,872
FFL	1ST FLOOR	912	912		99.04	90,329
TQS	3/4 STORY	684	912		74.28	67,747
Ttl. Gross Liv/Lease Area:		1,596	2,832	1,807		178,974

