

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	05		CAPE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	1.50		1 1/2 STORIES	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	3		ALUMINUM	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2				COST/MARKET VALUATION			
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:			105.68
Interior Floor 2							
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A	Replace Cost			166,872
AC Type	03		FULL	AYB			1953
Bedrooms	4			EYB			1980
Full Baths	2			Dep Code			AG
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	7			Dep %			37
Bath Style	G		GOOD	Functional Obslnc			
Kitchen Style	A		AVERAGE	External Obslnc			
Kitchens	1			Cost Trend Factor			1
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor				Overall % Cond			63
Bsmt Garage				Apprais Val			105,100
Units	1			Dep % Ovr			0
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr			0
Fireplaces	1			Misc Imp Ovr Comment			
				Cost to Cure Ovr			0
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	80	7.48	1955	A		AV	60	400

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	912		21.09	19,234
EFP	ENCL PORCH	0	96		31.92	3,065
FFL	1ST FLOOR	912	912		105.68	96,382
HST	HALF STORY	456	912		52.84	48,191
Ttl. Gross Liv/Lease Area:		1,368	2,832	1,579		166,872

