

[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	15		OLD STYLE	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft	502		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	2		CONC BLOCK	MIXED USE			
Exterior Wall 1	1		WOOD SHING	Code	Description		Percentage
Exterior Wall 2	2		CLAPBOARD	101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		87.22	
Interior Floor 2							
Heat Fuel	2		GAS	Replace Cost		133,092	
Heat Type	5		STEAM	AYB		1930	
AC Type	01		NONE	EYB		1994	
Bedrooms	3			Dep Code		GV	
Full Baths	1			Remodel Rating			
Half Baths	1			Year Remodeled			
Extra Fixtures	0			Dep %		23	
Total Rooms	6			Functional Obslnc			
Bath Style	A		AVERAGE	External Obslnc		5	
Kitchen Style	A		AVERAGE	Cost Trend Factor		1	
Kitchens	1			Condition			
Extra Kitchens	0			% Complete			
Frame	1		WOOD	Overall % Cond		72	
Basement Floor	12		CONCRETE	Apprais Val		95,800	
Bsmt Garage				Dep % Ovr		0	
Units	1			Dep Ovr Comment			
WS Flues				Misc Imp Ovr		0	
FBM Quality	3			Misc Imp Ovr Comment			
Fireplaces	0			Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
03	GARAGE	OB	Outbuilding	L	360	28.18	1930	A		FR	50	5,100

BUILDING SUB-AREA SUMMARY SECTION						
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
BMT	BASEMENT	0	717		17.39	12,472
EFP	ENCL PORCH	0	175		26.41	4,622
FFL	1ST FLOOR	717	717		87.22	62,534
OFF	OPEN PORCH	0	40		8.72	349
SFL	2ND FLOOR	609	609		87.22	53,115

Ttl. Gross Liv/Lease Area:		1,326	2,258	1,526		133,092
----------------------------	--	-------	-------	-------	--	---------

