

Print Date: 12/06/2018 13:21

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.50		1 1/2 STORIES	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	4		VINYL	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2				Adj. Base Rate:				116.23
Interior Floor 1	3		HARDWOOD	Replace Cost				148,423
Interior Floor 2	4		CARPET	AYB				1952
Heat Fuel	1		OIL	EYB				1975
Heat Type	1		FORCED H/A	Dep Code				AV
AC Type	01		NONE	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	1			Dep %				43
Half Baths	0			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	6			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				57
Extra Kitchens	0			Apprais Val				84,600
Frame	1		WOOD	Dep % Ovr				0
Basement Floor				Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality				Cost to Cure Ovr Comment				
Fireplaces	0							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
03	GARAGE	OB	Outbuilding	L	240	28.18	1955	A		AV	60	4,100

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	747		23.18	17,318	
FFL	1ST FLOOR	747	747		116.23	86,822	
HST	HALF STORY	374	747		58.19	43,469	
PAT	PATIO	0	144		5.65	814	
Ttl. Gross Liv/Lease Area:		1,121	2,385	1,277		148,423	

