

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B		GOOD	FBM Sqft	1425		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2	16		STONE VENR	101	ONE FAM		100
Roof Structure	6		SALTBOX				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL	COST/MARKET VALUATION			
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:		107.89	
Interior Floor 2	2		SOFTWOOD				
Heat Fuel	2		GAS				
Heat Type	3		FORCED H/W	Replace Cost		382,244	
AC Type	03		FULL	AYB		1980	
Bedrooms	3			EYB		1996	
Full Baths	2			Dep Code		GD	
Half Baths	1			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	7			Dep %		22	
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			
Kitchens	1			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond		78	
Bsmt Garage	2			Apprais Val		298,200	
Units	1			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality	3			Misc Imp Ovr		0	
Fireplaces	2			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION						
<i>Code</i>	<i>Description</i>	<i>Living Area</i>	<i>Gross Area</i>	<i>Eff. Area</i>	<i>Unit Cost</i>	<i>Undeprec. Value</i>
BMT	BASEMENT	0	2,041		21.57	44,018
FFL	1ST FLOOR	2,041	2,041		107.89	220,198
OPF	OPEN PORCH	0	95		11.36	1,079
OSP	SCRN PORCH	0	184		16.42	3,021
SFL	2ND FLOOR	1,056	1,056		107.89	113,929

<i>Ttl. Gross Liv/Lease Area:</i>		3,097	5,417	3,543		382,244

