

Property Location: 200 MAPLESHADE AV										MAP ID: 36/ 12/ 0/ /										Bldg Name:										State Use: 101																													
Vision ID: 2931										Account #2981										Bldg #: 1 of 1										Sec #: 1 of 1										Card 1 of 1										Print Date: 12/07/2018 09:28									
CURRENT OWNER										TOPO.					UTILITIES					STRT./ROAD					LOCATION					CURRENT ASSESSMENT										1006 4ST LONGMEADOW, M <																			

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)							
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description				
Style	19		RANCH	#Heat Sys	1						
Model	01		RESIDENTIAL	Central Vac	0		NO				
Grade	C		AVERAGE	FBM Sqft	609						
Stories	1.00		1 STORY	Int vs Ext	S		SAME				
Foundation	1		CONCRETE	MIXED USE							
Exterior Wall 1	3		ALUMINUM	Code	Description		Percentage				
Exterior Wall 2				101	ONE FAM		100				
Roof Structure	1		GABLE	COST/MARKET VALUATION							
Roof Cover	1		ASPHALT SH								
Interior Wall 1	2		PLASTER								
Interior Wall 2											
Interior Floor 1	4		CARPET								
Interior Floor 2	3		HARDWOOD								
Heat Fuel	2		GAS								
Heat Type	1		FORCED H/A								
AC Type	03		FULL								
Bedrooms	2										
Full Baths	1										
Half Baths	1										
Extra Fixtures	1										
Total Rooms	5										
Bath Style	A		AVERAGE								
Kitchen Style	A		AVERAGE								
Kitchens	1										
Extra Kitchens	0										
Frame	1		WOOD								
Basement Floor	12		CONCRETE								
Bsmt Garage											
Units	1										
WS Flues											
FBM Quality	1										
Fireplaces	1										
								Adj. Base Rate:		103.12	
								Replace Cost		194,699	
				AYB		1955					
				EYB		1975					
				Dep Code		AV					
				Remodel Rating							
				Year Remodeled							
				Dep %		43					
				Functional ObsInc							
				External ObsInc							
				Cost Trend Factor		1					
				Condition							
				% Complete							
				Overall % Cond		57					
				Apprais Val		111,000					
				Dep % Ovr		0					
				Dep Ovr Comment							
				Misc Imp Ovr		0					
				Misc Imp Ovr Comment							
				Cost to Cure Ovr		0					
				Cost to Cure Ovr Comment							

BUILDING SUB-AREA SUMMARY SECTION												
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value						
BMT	BASEMENT	0	1,218		20.66	25,162						
FFL	1ST FLOOR	1,446	1,446		103.12	149,118						
GAR	GARAGE	0	480		41.25	19,800						
OFP	OPEN PORCH	0	60		10.31	619						

		Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value
Ttl. Gross Liv/Lease Area:		1,446	3,204	1,888		194,699

