

VISION

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)				
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description	
Style	05		CAPE	#Heat Sys	1			
Model	01		RESIDENTIAL	Central Vac	0		NO	
Grade	C		AVERAGE	FBM Sqft				
Stories	1.75		1 3/4 STORIES	Int vs Ext	S		SAME	
Foundation	1		CONCRETE	MIXED USE				
Exterior Wall 1	2		CLAPBOARD	Code	Description		Percentage	
Exterior Wall 2				101	ONE FAM		100	
Roof Structure	1		GABLE	COST/MARKET VALUATION				
Roof Cover	1		ASPHALT SH					
Interior Wall 1	1		DRYWALL					
Interior Wall 2	4		SOLID WOOD	Adj. Base Rate:				110.53
Interior Floor 1	3		HARDWOOD	Replace Cost				175,852
Interior Floor 2	2		SOFTWOOD	AYB				1978
Heat Fuel	2		GAS	EYB				1988
Heat Type	1		FORCED H/A	Dep Code				AG
AC Type	01		NONE	Remodel Rating				
Bedrooms	3			Year Remodeled				
Full Baths	2			Dep %				30
Half Baths	0			Functional Obslnc				
Extra Fixtures	0			External Obslnc				
Total Rooms	6			Cost Trend Factor				1
Bath Style	A		AVERAGE	Condition				
Kitchen Style	A		AVERAGE	% Complete				
Kitchens	1			Overall % Cond				70
Extra Kitchens	0			Apprais Val				123,100
Frame	1		WOOD	Dep % Ovr				0
Basement Floor	12		CONCRETE	Dep Ovr Comment				
Bsmt Garage				Misc Imp Ovr				0
Units	1			Misc Imp Ovr Comment				
WS Flues				Cost to Cure Ovr				0
FBM Quality				Cost to Cure Ovr Comment				
Fireplaces	1							

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
02	SHED/FR			L	128	7.48	1986	A		AV	60	600

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	816		22.08	18,016	
FFL	1ST FLOOR	816	816		110.53	90,192	
TQS	3/4 STORY	612	816		82.90	67,644	
Ttl. Gross Liv/Lease Area:		1,428	2,448	1,591		175,852	

