

	Total Card Land Units:	0.17 AC	Parcel Total Land Area:	0.17 AC						Total Land Value:	73,300
--	-------------------------------	----------------	--------------------------------	----------------	--	--	--	--	--	--------------------------	---------------

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	12		MULTI-CONV	#Heat Sys	2		
Model	03		MULTI-FAMILY	Central Vac	0		NO
Grade	C		AVERAGE	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	3		MASONRY	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				104	TWO FAM		100
Roof Structure	1		GABLE				
Roof Cover	1		ASPHALT SH				
Interior Wall 1	2		PLASTER				
Interior Wall 2	1		DRYWALL	COST/MARKET VALUATION			
Interior Floor 1	2		SOFTWOOD	Adj. Base Rate:		93.30	
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	5		STEAM	Replace Cost		207,135	
AC Type	01		NONE	AYB		1910	
Bedrooms	4			EYB		1981	
Full Baths	2			Dep Code		AG	
Half Baths	0			Remodel Rating			
Extra Fixtures	0			Year Remodeled			
Total Rooms	8			Dep %		37	
Bath Style	A		AVERAGE	Functional ObsInc			
Kitchen Style	A		AVERAGE	External ObsInc			
Kitchens	2			Cost Trend Factor		1	
Extra Kitchens	0			Condition			
Frame	1		WOOD	% Complete			
Basement Floor	12		CONCRETE	Overall % Cond		63	
Bsmt Garage				Apprais Val		130,500	
Units	2			Dep % Ovr		0	
WS Flues				Dep Ovr Comment			
FBM Quality				Misc Imp Ovr		0	
Fireplaces	0			Misc Imp Ovr Comment			
				Cost to Cure Ovr		0	
				Cost to Cure Ovr Comment			

[illegible]

BUILDING SUB-AREA SUMMARY SECTION						
<i>Code</i>	<i>Description</i>	<i>Living Area</i>	<i>Gross Area</i>	<i>Eff. Area</i>	<i>Unit Cost</i>	<i>Undeprec. Value</i>
BMT	BASEMENT	0	1,080		18.66	20,154
FFL	1ST FLOOR	1,080	1,080		93.30	100,768
OPF	OPEN PORCH	0	168		9.44	1,586
SFL	2ND FLOOR	907	907		93.30	84,627

<i>Ttl. Gross Liv/Lease Area:</i>	1,987	3,235	2,220		207,135

