


[illegible]

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	1		YES
Grade	C+		AVG. (+)	FBM Sqft	693		
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	3		HARDWOOD	Adj. Base Rate:		93.08	
Interior Floor 2	4		CARPET				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A				
AC Type	03		FULL				
Bedrooms	4			Replace Cost	334,808		
Full Baths	3			AYB	1994		
Half Baths	0			EYB	2004		
Extra Fixtures	1			Dep Code	GD		
Total Rooms	8			Remodel Rating			
Bath Style	G		GOOD	Year Remodeled			
Kitchen Style	G		GOOD	Dep %	14		
Kitchens	1			Functional ObsInc			
Extra Kitchens	0			External ObsInc			
Frame	1		WOOD	Cost Trend Factor	1		
Basement Floor				Condition			
Bsmt Garage				% Complete			
Units	1			Overall % Cond	86		
WS Flues				Apprais Val	287,900		
FBM Quality	1			Dep % Ovr	0		
Fireplaces	1			Dep Ovr Comment			
				Misc Imp Ovr	0		
				Misc Imp Ovr Comment			
				Cost to Cure Ovr	0		
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,385		18.62	25,783	
CFL	CATHEDRAL CE	260	260		95.94	24,945	
FFL	1ST FLOOR	1,110	1,110		93.08	103,319	
GAR	GARAGE	0	864		37.28	32,206	
HST	HALF STORY	432	864		46.54	40,210	
OFP	OPEN PORCH	0	15		12.41	186	
SFL	2ND FLOOR	1,125	1,125		93.08	104,715	
WDK	WOOD DECK	0	266		12.95	3,444	

Ttl. Gross Liv/Lease Area:		2,927	5,889	3,597		334,808	
----------------------------	--	-------	-------	-------	--	---------	--



75 WINDHAM DR