

CONSTRUCTION DETAIL				CONSTRUCTION DETAIL (CONTINUED)			
Element	Cd.	Ch.	Description	Element	Cd.	Ch.	Description
Style	06		COLONIAL	#Heat Sys	1		
Model	01		RESIDENTIAL	Central Vac	0		NO
Grade	B-		GOOD (-)	FBM Sqft			
Stories	2.00		2 STORY	Int vs Ext	S		SAME
Foundation	1		CONCRETE	MIXED USE			
Exterior Wall 1	4		VINYL	Code	Description		Percentage
Exterior Wall 2				101	ONE FAM		100
Roof Structure	1		GABLE	COST/MARKET VALUATION			
Roof Cover	1		ASPHALT SH				
Interior Wall 1	1		DRYWALL				
Interior Wall 2							
Interior Floor 1	4		CARPET	Adj. Base Rate:		97.20	
Interior Floor 2	3		HARDWOOD				
Heat Fuel	2		GAS				
Heat Type	1		FORCED H/A				
AC Type	03		FULL	Replace Cost	330,567		
Bedrooms	4			AYB	2003		
Full Baths	2			EYB	2009		
Half Baths	1			Dep Code	GD		
Extra Fixtures	0			Remodel Rating			
Total Rooms	8			Year Remodeled			
Bath Style	A		AVERAGE	Dep %	9		
Kitchen Style	A		AVERAGE	Functional ObsInc			
Kitchens	1			External ObsInc			
Extra Kitchens	0			Cost Trend Factor	1		
Frame	1		WOOD	Condition			
Basement Floor	12		CONCRETE	% Complete			
Bsmt Garage				Overall % Cond	91		
Units	1			Apprais Val	300,800		
WS Flues				Dep % Ovr	0		
FBM Quality				Dep Ovr Comment			
Fireplaces	1			Misc Imp Ovr	0		
				Misc Imp Ovr Comment			
				Cost to Cure Ovr	0		
				Cost to Cure Ovr Comment			

OB-OUTBUILDING & YARD ITEMS(L) / XF-BUILDING EXTRA FEATURES(B)												
Code	Description	Sub	Sub Descript	L/B	Units	Unit Price	Yr	Gde	Dp Rt	Cnd	%Cnd	Apr Value
19	PATIO			L	420	5.75	2007	A		GD	70	1,700

BUILDING SUB-AREA SUMMARY SECTION							
Code	Description	Living Area	Gross Area	Eff. Area	Unit Cost	Undeprec. Value	
BMT	BASEMENT	0	1,232		19.41	23,910	
FFL	1ST FLOOR	1,232	1,232		97.20	119,747	
GAR	GARAGE	0	768		38.85	29,839	
HST	HALF STORY	384	768		48.60	37,324	
SFL	2ND FLOOR	1,232	1,232		97.20	119,747	
Ttl. Gross Liv/Lease Area:		2,848	5,232	3,401		330,567	

